



Northbrook  
Division  
333 Pfingsten Road  
Northbrook, IL 60062-2096  
USA  
www.ul.com  
tel: 1 847 272 8800  
fax: 1 847 272 8129  
Customer service: 1 877 854  
3577

File SA11613

Vol 1

Issued: 1996-05-10

Revised: 2005-08-26

FOLLOW-UP SERVICE PROCEDURE  
(TYPE R)

PANIC HARDWARE  
(FVSR, FVSR7)

Manufacturer: SEE ADDENDUM FOR MANUFACTURING LOCATIONS

Applicant: [REDACTED]  
(268271-001) [REDACTED]  
[REDACTED]  
[REDACTED]

Listee: SAME AS APPLICANT  
(268271-001)

This Procedure authorizes the above Manufacturer to use the marking specified by Underwriters Laboratories Inc. only on products covered by this Procedure, in accordance with the applicable Follow-Up Service Agreement.

The prescribed Mark or Marking shall be used only at the above manufacturing location on such products which comply with this Procedure and any other applicable requirements.

The Procedure contains information for the use of the above named Manufacturer and representatives of Underwriters Laboratories Inc. and is not to be used for any other purpose. It is lent to the Manufacturer with the understanding that it is not to be copied, either wholly or in part, and that it will be returned to Underwriters Laboratories Inc. upon request.

This PROCEDURE, and any subsequent revisions, is the property of UNDERWRITERS LABORATORIES INC. and is not transferable.

UNDERWRITERS LABORATORIES INC.

Sajeesh Jesudas  
Chief Operating Officer

An independent organization working for a safer world with integrity, precision and knowledge.





FILE SA11613

VOL 1

ADDENDUM TO PAGE 1  
AUTHORIZATION PAGE

ISSUED: 1996-05-10

REVISED: 2005-08-26

LOCATION

(100034-085)

SHANGHAI TIANHUA WIRELESS CO. LTD.  
100 HAILANG RD.  
HONGKONG 999  
HONGKONG CHINA

(268271-001)

SHANGHAI CHONG CO. LTD.  
100 HAILANG RD.  
HONGKONG 999  
HONGKONG CHINA

ARROW  
H  
A  
ONG



Model or Cat. No.	Section	USL/CNL	UL305	ANSI/BHMA - Grade 1, 2, 3*
UL510X	1	USL/CNL	x	N/A
UL500X, UL500-1X	1	USL/CNL	x	1
A-UL500X, A-UL500-1X	1	USL/CNL	x	1
UL560X, UL560-1X	2	USL/CNL	x	N/A
A-UL560X, A-UL560-1X	2	USL/CNL	x	1

\* - These devices have been examined in accordance with ANSI/BHMA A156.3(2001), Grade 1 or 2 or 3 requirements.